

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch

690 Walnut Ave. St. 150

Vallejo, CA 94592-1133

(707) 649-5453

(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-021294**Date Inspected:** 10-Jan-2011**Project Name:** SAS Superstructure**OSM Arrival Time:** 1500**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 300**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Qiu Wen**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG Segment Assembly**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector, Ramesh Gade, was present during the times noted above for observations relative to the work being performed.

OBG Segment 13AW / Bay 14

This QA inspector performed Magnetic Particle Testing (MT) approximately 15% of the area that has been previously tested and accepted by ZPMC Quality Control (QC) personnel. This QA Inspector generated MT report for this date. The member is identified as OBG Segment 13AW as per ZPMC notification # 0821.

The weld designations reviewed are as follows:

SEG3013AW-081, 084, 022

SEG3013RS3486-002

SEG3013AW-080, 023, 085, 093, 092, 019

SEG3013AX-177, 049, 180, 050, 190, 053

SEG3013RS3484-002, 001

SEG3013AT-069, 071

OBG Segment 13AW / Bay 14

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

This QA inspector performed Magnetic Particle Testing (MT) approximately 15% of the area that has been previously tested and accepted by ZPMC Quality Control (QC) personnel. This QA Inspector generated MT report for this date. The member is identified as OBG Segment 13AE Deck Panel Diaphragm welds as per ZPMC notification # 08124.

The weld designations reviewed are as follows:

DP3074-145~149, 152~157, 160~165, 168~173, 176~178
DP3074-227~231, 236~241, 246~251, 256~261, 265~267
DP3074-269~273, 278~283, 286, 289~293, 298~303, 308~310
DP3074-311~315, 320~325, 330~335, 340~345, 350~352

OBG Segment 13AW / Bay 14

This QA Inspector observed the following work in progress:

Flux Core Arc Welding (FCAW) in the 3G position of weld # SEG3013AW-041. The welder is identified as 069712. ZPMC Quality Control (QC) is identified as Zhang Lin. The welding variables recorded by QC appeared to comply with WPS-B-T-2233-ESAB.

OBG Segment 13AW / Bay 14

This QA Inspector observed the following work in progress:

Flux Core Arc Welding (FCAW) in the 2G position of weld # SEG3013AW-084. The welder is identified as 066239. ZPMC Quality Control (QC) is identified as Zhang Lin. The welding variables recorded by QC appeared to comply with WPS-B-T-2232-ESAB.

OBG Segment 14W / Bay 14

This QA Inspector observed the following work in progress:

Shielded Metal Arc Welding (SMAW) in the 3G position of repair weld # SEG3020Q-058, as per B-CWR # 2620. The welder is identified as 037780. ZPMC Quality Control (QC) is identified as Zhang Lin. The welding variables recorded by QC appeared to comply with WPS-345-SMAW-3G(3F)-FCM-Repair-1.

OBG Segment 14W / Bay 14

This QA Inspector observed the following work in progress:

Flux Core Arc Welding (FCAW) in the 2G position of weld # SEG3020BB-028. The welder is identified as 067103. ZPMC Quality Control (QC) is identified as Zhang Lin. The welding variables recorded by QC appeared to comply with WPS-B-T-2232-ESAB

Summary of Conversations:

No relevant conversations reported on this date.

Comments

WELDING INSPECTION REPORT

(Continued Page 3 of 3)

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang (+86)15000 42 2372, who represents the Office of Structural Materials for your project.

Inspected By:	Gade,Ramesh	Quality Assurance Inspector
Reviewed By:	McClendon,Timothy	QA Reviewer
